



Town of Strathmore

680 Westchester Road
Strathmore, AB T1P 1J1
Phone: (403) 934-3133

Fax: (403)934-4713
email: serviceconnect@strathmore.ca

WATER, SANITARY SEWER & STORM SEWER CONNECTION INSPECTIONS

- All water, sanitary & storm connections to be completed and installed to specifications on WATER, SANITARY SEWER & STORM SEWER CONNECTION CHECKLIST
- All service connections to be performed by a licensed plumber
- Upon completion of connection and PRIOR to backfilling, access will be provided to the Service Connections Inspector to perform a scheduled inspection
- If the service connection passes the inspection it may be backfilled
- If the service connection fails the inspection the service must be corrected and re-inspected prior to backfilling

PLUMBING QUICK TRENCH (AUDIT INSPECTION)

An excavation contractor who has completed FIVE consecutive service connections in the Town of Strathmore which have been accepted by the Service Connections Inspector may perform the excavation and installation of water, sanitary sewer and storm sewer connections as per the conditions of the Quick Trench program:

- The Service Connections Inspector to be notified 48 hours prior to commencement of service inspection
- All water, sanitary & storm connections to be completed and installed to specifications on WATER, SANITARY SEWER & STORM SEWER CONNECTION CHECKLIST
- The Service Connections Inspector will perform intermittent audit inspections or request that a trench not be backfilled for a scheduled TWO hour inspection period
- If the inspection fails, an inspection notice will be left with the contractor. The trench shall not be backfilled until the connection is corrected and passes a re-inspection
- If the trench is backfilled prior to the connection being corrected OR passing a re-inspection the contractor must dig up the back fill and expose all piping in the trench in question AND their previous THREE trenches
- If the Service Connections Inspector has not requested an inspection, the Quick Connect contractor may complete the connection as per the attached specifications and backfill without inspection, however pictures must be submitted immediately to serviceconnect@strathmore.ca with the civic address in the subject line
- Pictures must include clear photos of the following: entire length of the trench with services installed prior to backfilling, details of all connections and fitting as well as the approximate depth of the trench
- If the Service Connections Inspector finds any deficiencies with the pictures, the Town of Strathmore reserves the right to ask that the back fill be dug up and the service corrected.